



# Step 0 Distinguish Between Front And Back

Parts List

Acrylic Base Plate\*2

Splicing  
Diagram




Notes


This is the front side as shown in the picture above and is assembled with the front side facing up.

| Step 1 Mounting The Motor |   |                 |                            |
|---------------------------|---|-----------------|----------------------------|
| Parts List                | N20 Motor*2   | Motor Bracket*2 | M2 Nuts*4                  |
|                           | M2*10 Flat Head Cross Screws*4  |                 | Acrylic Lower Base Plate*1 |
| Splicing Diagram          |   |                 |                            |
| Notes                     | <p>1. Note that you need to place the nut into the corresponding position of the bracket hole before allowing the screw to pass through as shown in the diagram;</p> <p>2. Note the orientation of the motor mount.</p> |                 |                            |


## Step 2 Mounting The Trace Sensor

|                  |  |                                  |
|------------------|--|----------------------------------|
| Parts List       | Trace Sensor*1   | M3*7 Double Pass Copper Column*4 |
|                  | M3*6 Flat Head Cross Screws*8  | 5PIN XH2.54 to Dupont Cable*1    |
| Splicing Diagram |   |                                  |
| Notes            | <ol style="list-style-type: none"><li>1. First install the screws and copper post on the base plate in the picture;</li><li>2. Then align the tracing module with the copper post holes and lock the screws;</li><li>3. Finally, you can connect the snap-in cable to the interface of the module.</li></ol> |                                  |


### Step 3 Mounting Universal Wheel

| Parts List       | Universal Wheel*1   | M3*7 Double Pass Copper Column*2 | M3*6 Flat Head Cross Screws*4 |
|------------------|---|----------------------------------|-------------------------------|
| Splicing Diagram |    |                                  |                               |
| Notes            | <p>1. First install the screws and copper post on the base plate in the picture;<br/>2. Then align the universal wheel with the brass post holes and lock the screws.</p> |                                  |                               |

## Step 4 Mounting The Motor Drive Module

| Parts List       | L298N Motor Drive Module*1  | M3*7 Double Pass Copper Column*4 | M3*6 Flat Head Cross Screws*8 |
|------------------|---|----------------------------------|-------------------------------|
| Splicing Diagram |    |                                  |                               |
| Notes            | <ol style="list-style-type: none"><li>1. First install the screws and copper post on the base plate in the picture;</li><li>2. Then align the motor drive plate with the copper post holes and lock the screws.</li><li>3. Pay attention to the orientation of the motor drive plate.</li></ol> |                                  |                               |

## Step 5 Mounting Controller Board And Expansion Board

|                  |  |                               |
|------------------|--|-------------------------------|
| Parts List       | ESP32 Controller Board*1   | Expansion Board*1             |
|                  | M3*7 Double Pass Copper Column*4   | M3*6 Flat Head Cross Screws*8 |
| Splicing Diagram |  The diagram shows a three-tier assembly. At the bottom is a circular bottom plate with several pre-drilled holes. Four copper columns are shown being inserted into these holes. Eight screws are shown being inserted into the plate, four on each side of the copper columns. On top of the copper columns, an expansion board is mounted. The expansion board has two rows of pins. An ESP32 controller board is shown being inserted into the top row of pins. A red arrow points downwards from the controller board towards the expansion board, indicating the direction of assembly. |                               |
| Notes            | <ol style="list-style-type: none"><li>1. First, install the screws and copper posts on the bottom plate in the picture;</li><li>2. Then align the expansion board with the copper post holes and lock the screws;</li><li>3. Finally, insert the motherboard into the corresponding holes of the expansion board.</li></ol>  |                               |


## Step 6 Mounting Supporting Copper Columns

Parts  
List

M3\*40 Double Pass Copper  
Column\*4


M3\*10 Flat Head Cross Screws\*4

Splicing  
Diagram




Notes

## Step 7 Mounting the Battery Box

| Parts List       | Acrylic Upper Base Plate*1  | M3*10 Flat Head Cross Screws*4 |
|------------------|---|--------------------------------|
|                  | M3 Nuts*4   | 18650 Battery Box*1            |
| Splicing Diagram |    |                                |
| Notes            | <p>1. Pay attention to distinguish the front and back of the base plate (if you forget, please refer to the first step);</p> <p>2. Pay attention to the orientation of the battery box.</p> |                                |




## Step 8 Mounting the Servo

| Parts List       | Servo*1   | M2*10 Round Head Cross Screws*2 | M2 Nuts*2 |
|------------------|---|---------------------------------|-----------|
| Splicing Diagram |  |                                 |           |
| Notes            | 1. Note the orientation of the servo shaft.   |                                 |           |

## Step 9 Mounting Ultrasonic Sensor

### 9.1 Fixed Ultrasonic Sensor

|                  |  |                             |
|------------------|--|-----------------------------|
| Parts List       | Ultrasonic Sensor*1  | Ultrasonic Sensor Bracket*1 |
|                  | M1.6*10 Round Head Cross Screws*4  | M1.6 Nuts*4                 |
| Splicing Diagram |  |                             |
| Notes            |  |                             |

## Step 9 Mounting Ultrasonic Sensor


### 9.2 Mounting the Servo Rocker Arm

Parts  
List

"1" Shaped Servo Rocker  
Arm\*1

M1.4\*5 Self-Tapping Screw\*2

Splicing  
Diagram



Notes


## Step 9 Mounting Ultrasonic Sensor

### 9.3 Fixed Ultrasonic Sensor Bracket

Parts  
List


Small screw from servo package\*1

Splicing  
Diagram




Notes

## Step 10 Mounting the IR Receiver Module

|                  |   |                                 |           |
|------------------|---|---------------------------------|-----------|
| Parts List       | IR Receiver Module*1  | M2*10 Round Head Cross Screws*2 | M2 Nuts*2 |
| Splicing Diagram |  |                                 |           |
| Notes            | 1. Note the orientation of the IR module.   |                                 |           |

## Step 11 Wiring

Wiring Diagram



Notes


1. Note the distinction between XH2.54 terminal wire and DuPont wire
2. Note that the ESP32 board and L298N motor driver board need to be connected to the battery cable

## Step 12 Combine Upper And Lower Base Plates

Parts  
List


M3\*10 Flat Head Cross Screws\*4

Wiring  
Diagram



Notes

# Step 13 Mounting Wheels

|                |  |
|----------------|--|
| Parts List     | Wheels*2   |
| Wiring Diagram |  |
| Notes          |  |

