

- 1、 Pls find the installation package and double-click to enter.
- 2. Enter into the 1st step of installation, then click"Next".



3. Enter into the 2nd step of installation, and click"Next" after log in user info.

Solar Station Monitor Setup
User Information Enter your user information and click Next to continue
Inter your user information and trick mext to continue.
Name:
SR-ML
Company:
SRNE
< <u>B</u> ack <u>M</u> ext > Cancel

4. Click"Next" after choosing installation directory.



5、 Click"Next" after choosing path folder.



6、 Click "Next" after confirming installation info.



7、 When installation finished, click "Finish" to exit.



8. If your system is WINDOWS 7 or above, the system may have superior authority management on software, you need to install below setting to use the software.

Step 1: Find the software icon of Solar Station Monitor, a dialog box will be shown after click the right click of the mouse, then pls find "Properties" and click it.



Step 2: Choose "Compatibility" under property dialog box and click it to enter the setting for software compatibility.

8	Solar Station Monitor					
Security	Deta	Details		Previous Versions		
General	Shortcut	Comp	atibility	File Hashes		
If you have problems with this program and it worked correctly on an earlier version of Windows, select the compatibility mode that matches that earlier version.						
Compatibility mode						
Hun this program in compatibility mode for:						
Windows XP (Service Pack 3)						
Settings						
Run in 256 colors						
Run in 640 x 480 screen resolution						
Disable visual themes						
Disable desktop composition						
Disable display scaling on high DPI settings						
Run this program as an administrator						
Change settings for all users						
OK Cancel Apply						

Step 3: Find the "Run this program as an administrator" under upper computer software property dialog box, and then select it.

Step 4: When above steps finished, click "OK" to exit.

9. If the software still not work, then you should enter into software installation catalog and find "OcxDllInstall.exe", click the right click to find "Run as administrator" to operate, the system will re-log widget.

	_	
		Open
OcxDllInstall.exe	۲	Run as administrator
		ካያ Share
		Pin to Start Menu
		Add to Quick Launch
		Restore previous versions
		Send To
		Cut
		Сору
		Create Shortcut
		Delete
		Rename
		Properties

10、 When installation finished, you need to install USB-RS232 driver, then the software works.