

Functions	Range	Resolution	Accuracy
Wind Speed	0 ~ 30m/s	0.1m/s	±5%rdg+0.5
Temperature	-10 ~ 50°C	0.1°C	±2°C
	14 ~ 122°F	0.2°F	±4°F
Wind Scale	Level 0 ~ 12	1	±1
Sampling Rate			0.5s
Overload Indication	> 45m/s		OL
MAX/AVG			MAX/AVG
Data Hold			HOLD
LCD Backlight			Yes
Auto Power Off			5min
Low Battery Indication			3.0 ~ 3.5V
Battery			4.5V
Current Consumption	Working	mA	≤25mA
	Power off	uA	≤10uA
Work Environment	Temperature		0 ~ 40°C
	Humidity		≤80%RH
Storage Environment	Temperature		-20 ~ 60°C
	Humidity		≤75%RH
<b>Key Functions</b>			
ON/OFF	Short press to turn on/off the meter		
MAX/AVG	Short press to switch between MAX/MIN/QUIT		

UNIT	Short press switch between m/s, ft/m, mph, Km/h, Knots , °C , °F.
HOLD/BL	Short press to turn on/off backlight