

**TP100 Soldering Iron**



- Safety cap
- Adjustable gas flow
- Flint
- Self ignitor
- Ronsons butane gas recommended

**Technical Overview**

<b>Operating Temperature</b>	200 - 450°C
<b>Operating Time</b>	30 minutes

**TP100K Soldering Kit**



- Adjustable gas flow
- Flint
- Self ignitor
- Handy carry case
- Ronsons butane gas recommended
- Refer to **TP100** for technical overview

**Model Specification**

<b>Standard Accessories</b>	Solder, Deflector, Hot knife, Chisel Tip, Angle Tip, Stand, Sponge, Handy Carry Case
-----------------------------	--

**TP200 Soldering Iron**



- Safety cap
- Adjustable gas flow
- Flint
- Self ignitor
- Ronsons butane gas recommended

**Technical Overview**

<b>Operating Temperature</b>	200 - 450°C
<b>Operating Time</b>	50 minutes

**TP200K Soldering Kit**



- Handy carry case
- Ronsons butane gas recommended
- Adjustable Flow
- Hot Blower
- Self ignitor
- Refer to **TP200** for technical overview

**Model Specification**

<b>Standard Accessories</b>	Solder, Hot knife, 2.4mm Chisel, 3.0 Angle Tip, Deflector, Hot Blow, Stand, Sponge, Handy Carry Case
-----------------------------	--