



<b>600W PSW Power Inverter</b>		<b>600W 12V</b>	<b>600W 24V</b>	<b>600W 48V</b>
<b>AC Output</b>	Continuous power:	600W		
	Surge power:	1200W		
	Max Constant Power Start :	720W for 10 seconds		
	Output Waveform	Pure Sine Wave (THD < 3%)		
	Output Frequency	50Hz±0.1% or 60Hz±0.1% (Optional)		
	AC Output Voltage	100~120VAC / 200~240VAC (Optional)		
<b>DC Input</b>	DC Input Voltage	12V DC	24V DC	48V DC
	Voltage Range	10V-15V	20V-30V	40V-60V
	Low Voltage Alarm	10.5V±0.5V	21V±1V	42V±2V
	Low Voltage Shut down	10V±0.5V	20V±1V	40V±2V
	Over Voltage Shut down	15V±0.5V	30V±1V	60V±2V
	Over load shut down	720W over 10 seconds		
<b>Converting Max. Efficiency</b>		90% (Full Loading) / 95% (1/3 Loading)		
<b>No Load Consumption</b>		< 0.35A		
<b>Protection</b>	Over Thermal:	Shut Off Output Automatically, Temperature >75°C		
	Short circuit protection:	Reverse Polarity (External Fuse)		
	Cooling Fan automatically run	Temperature ≥45°C		
<b>Environment</b>	Working temperature	-10°C ~+50°C		
	Working humidity	20%~90% RH Non-Condensing		
	Storage Temperature Range	-30°C ~+70°C		
<b>LED Indicator Light</b>		Inverter, Fault		
<b>Packing</b>	Inner Box Dimensions (mm)	315*195*135 mm		
	Inner Box Weight (kg)	2.6 kg		